



The Rapid Alert System for Non-Food Products (RAPEX)

Notification Reference: A12/1063/15

| | |
|--|---|
| Risk level | Serious risk |
| Product user | Consumer |
| Notifying country | Portugal |
| Product category | Motor vehicles |
| Product | Passenger car |
| Brand | Chevrolet |
| Name | Captiva |
| Type/number of model | Unknown |
| Batch number/Barcode | Production years: 2011 to 2015. Vehicles from B B 002186 to F B 058052. |
| OECD Portal Category | 77000000 - Automotive |
| Description | Passenger car. |
| Country of origin | Republic of Korea |
| Counterfeit | |
| Risk type | Fire |
| Risk description | Malfunction of the diesel particulate filter could cause the lower engine compartment cover to overheat and catch fire. |
| Measures adopted by notifying country | Voluntary measures: Recall of the product from end users |
| Products were found and measures were taken also in | |
| Images | No pictures are available |